

VEHICLE INSPECTION REPORT

PJ71DTK

Mercedes-Benz Sprinter 317 2.0 TDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 15/11/2021

Year 2021

Mileage 158,574 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076332P381013

Body Style Panel Van MWB

MOT Due Expired

CAP Clean £10,950.00

CAP Average £9,900.00

CAP Below £8,350.00

Gearbox AUTOMATIC

Gears 6

SIDE LOAD DOOR, TOW BAR, REAR VIEW CAMERA, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm

2: Door osf
Dented
Over 2 UpTo 10mm




3: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%




4: Tailgate
Dented
Over 30mm



5: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



6: Door Moulding nsf
Broken
Replace



Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		