

VEHICLE INSPECTION REPORT

MXZ7282

Scania R 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/02/2019

Year 2019

Mileage 866,889 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YS2R6X20009248062

Body Style Tractor Unit

MOT Due Expired

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

NEAR BRIGHTON TWIN FUEL TANKS, AD BLUE, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2



OSO3


OSO4


Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: A Post ns
Dented
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK