COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SL75YPX

Ford Transit Custom 320 65KWH Sport

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Photocopy
Cap Id	57729
Cap Code	FOTU002S61VE A2 2 L

Details

Location	Livingston	**GVW**	3225kg	**CAP Clean**	£23,600.00
Reg. date	17/10/2025	**Colour**	GREY	**CAP Average**	£22,700.00
Year	2025	**VIN**	WF0RXXTA2BRY85779	**CAP Below**	£20,400.00
Mileage	12,847 Miles Not Warranted	**Body Style**	Panel Van L1	**Gearbox**	AUTOMATIC
Fuel Type	Electric	**MOT Due**	16/10/2028	**Gears**	1

SIDE LOAD DOOR, APPLE AND ANDROID CAR PLAY, E/MIRRORS, HEATED SEATS, REAR VIEW CAMERA, HEATED WINDSCREEN, TYPE 2 CHARGING CABLE PRESENT

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Front parking sensor
- Front electric windows
- Rear parking sensor
- Central locking
- Radio/CD
- Air conditioning

Photos










FORD
EKRA
e5*2018/858*00192
WF0RXXTA2BRY85779
3225
5350
1400
2000
W(mm)
L(mm)
D
3100
NRN










Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Bonnet
Chipped
Multiple Chips



3: Door nsr
Chipped
Edge Chip



4: Qtr Panel nsr
Cracked
Replace
Missing clips holding to body so it’s loose



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK

Windows	OK	Steering	OK

Commercial Vehicle Auctions Limited