

VEHICLE INSPECTION REPORT

PK67VGG

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/11/2017

Year 2017

Mileage 1,047,183 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181086

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/10/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4



Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Poor Previous Repair
Poor Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Door nsf
Dented
With Paint Damage

6: Door nsf
Chipped
Multiple Chips



7: Bumper Front
Dented
With Paint Damage

8: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



9: Door osf
Dented
Over 30mm

10: Door osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			